

# FITNESS CERTIFICATE OF SCHOOL BUILDING

(To be filled by the Inspecting Officer (Assistant Engineer))

1. Name of School : **TRINITY LYCEUM , NANTHIRIKKAL**
2. Name of Officer : **ARUN.R.T , Asst. Engineer, LID&EW Section  
Perinad Grama Panchayath**
3. Location with Educational District/ Sub district : **Perinad, Kundara, kollam**
4. Classification of buildings as specified in column For the application for fitness certificate and size : **THREE STORIED RCC ROOFED BUILDING – L SHAPED**  
1) 1 x 58.00 x 8.75 x 3.70 m (GF,FF,SF)  
2) 1 x 49.00 x 8.50 x 3.70m (GF,FF,SF)
5. Period for which certificate is issued : **2024-25**
6. Nature of Defects if any  
a. Foundation & Basement  
b. Superstructure  
c. Doors & Windows  
d. Wood work wrought & put up  
e. Roof  
f. Flooring  
g. Miscellaneous } : **NIL**
7. Any major defects noticed which will render the building unsafe in any manner. : **No**
8. Whether maintenance works have been done properly : **Yes**
9. Whether the structure is sound or not for conducting classes : **The structure is sound under normal wind and weather conditions.**

Certified that the school was inspected by me on 31/05/2024 and found to be fit to conduct classes for the period 2024-25 for the reasons stated above.

Place : Perinad

Date : 31/05/2024

Signature:

  
**ASSISTANT ENGINEER**  
Designation: **Local Self Govt. Dept.**  
**Perinad Grama Panchayath**

