FITNESS CERTIFICATE

To be fiiled by the Inspecting Officer (Asst.Engineer)

(Re:G.O.Ms.20/70/PWD Dt. 23-01-1970)

1.	Name of the Officer	Ajesh S., Asst. Engineer, LID&EW Section, Perinad GP
2.	Name of the School	Trinity Lyceum, Nanthirickal
3.	Location with name of Education District/Sub.District	Perinad, Kundara , Kollam
4.	Classification of Building as specified in column 4 of the Application for fitness certificate and size.	Three Sroried RCC Roofed Building L Shaped 1) 1x58.00x8.75x3.70 m(GF,FF,SF) 2) 1x49.00x8.5x3.70 m (GF,FF,SF)
5.	Period for which the certificate is issued	Academic Year 2026-2027
6.	Nature of defects, if any	
	a) Foundation and basement	Nil
	b) Superstructure	
	c) Doors and Windows	
	d) Wood work wrought and put up	
	e) Roof	
	f) Flooring	
	g) Miscellaneous (Cracks,etc.)	
7.	Any major defects noticed which will render the Building unsafe in any manner	No
	a) Whether maintenance works have been done properly	Yes
	b) Whether the structure is sound or not for conducting classes:	The Structure is sound under normal wind and weather Conditions

Note: ***1.The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2.Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.***

CERTIFICATE

Certified that the school building was inspected by me on 02/06/2026 and Found to be fit to conduct classes,for the period 2026-27 for the reasons stated above.

Place:Perinad

Date:04/07/2026

OFFICE OF THE ASSISTANT ENGINEER LID&EW PERINAD (Seal)

AJESH S. Assistant Engineer LID&EW Perinad GP PE-7647428

.....

Assistant Engineer